

TOP SECRET

PRIORITY

TOP SECRET 161942Z

PRIORITY

4968

IDEALIST

ATTENTION:

SUBJECT: EVALUATION OF MISSION C215C

1. CAMERA B 10 WAS USED IN MISSION C215C FLOWN ON 17 APRIL 1965. PROCESSING WAS ACCOMPLISHED IN THE FIELD.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: EDGE STATIC AND ROLLER CHATTER ARE PRESENT ON BOTH EDGES THROUGHOUT THE MISSION. THERE ARE FINE PLUS DENSITY LINES 0.7" LONG LOCATED 1.0" FROM THE OUTBOARD EDGE APPEARING IN FRAMES 005 TO 022. HEAT SPLICES ARE LOCATED BETWEEN 83/84, 216/217, 231/232, 349/350, 471/472, 482/483, 579/580, 615/616 AND 748/749.

C. 9L SIDE: ROLLER CHATTER APPEARS ON THE INBOARD EDGE INTERMITTENTLY THROUGHOUT THE MISSION. SEVERAL IRREGULAR PLUS DENSITY STREAKS ARE PRESENT ON THE OUTBOARD EDGE. HEAT SPLICES ARE BETWEEN FRAMES 83/84, 216/217, 221/222, 349/350, 482/483, 615/616, 633/634 AND 748/749.

D. BOTH SIDES: FAINT IMAGES OF POSITION INDICATORS ARE ALWAYS PRESENT WHEN THE CORRECT ONE IS EXPOSED. THERE IS ALSO FLARE PRESENT ON THE OUTBOARD EDGE RESULTING FROM THE VERTICAL DOT HOUSING. MINOR PROCESSING STREAKS APPEAR IN A FEW FRAMES AT BOTH SIDES OF THE MISSION.

1965 JUL 16 19 56Z

OUT 56190

25X1

25X1

19 JUL 1965

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC DR	
	PLDS	
	COO	
	LD	
	PSD	
34	IS	
	IN	
	PA	
	LM-4	
	SA	
	CMO	
	SAVP	

TOP SECRET

Excluded from automatic
downgrading and
declassification

E. THE FIRST TITLED FRAME IS 005 AND THE LAST TITLED FRAME IS 0854.

F. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY WAS GOOD WHERE NOT DEGRADED BY CLOUD COVER OR ATMOSPHERICS.

B. PRINTING AND PROCESSING WAS ADEQUATE.

C. CLOUD COVER WAS APPROXIMATELY 70 PERCENT.

T O P S E C R E T

/END OF MESSAGE/

1